



**Indiana Department of Labor and CCS
Monthly Partnership Report
January 2023**

The following companies are signatory to the IDOL/CCS Partnership Agreement:

AAA Roofing Co., Inc.

ABC Cutting Contractors, Inc.

Advanced Rescue Solutions

ATEC, INC.

AECOM Hunt

Allison Farms Lawn & Landscaping LLC

August Mack Environmental, Inc.

BMWC Constructors

Bowen Engineering Corporation

Brehob Corporation

Broady-Campbell, Inc.

Browning Chapman, LLC

Capital Machinery Systems

C&C Sheet Metal, LLC

Charah, LLC

CMS Corporation

D.A. Dodd, LLC

Denney Excavating Inc.

Diversified Painting Co.

****Edwards Electrical and Mechanical**

Electric Plus

Empire Contractors

ERMCO

Essential Architectural Signs, Inc.

F.A. Wilhelm Construction Co., Inc.

F.E. Moran, Inc. Fire Protection

F.E. Moran, Inc. Special Hazard Systems

Freitag-Weinhardt, Inc.

Gaylor Electric

Gibson-Lewis of Indianapolis, LLC

Gribbins Insulation Co., Inc.

GroundBreakers Hydrovac Excavation

Harmon Steel, Inc.

Harrell-Fish Inc.

Hoist & Crane Service Group, Inc.

Horning Roofing & Sheet Metal Co, LLC

Industrial Electric, Inc.

Interior Specialties, Inc.

J.F. Electric, Incorporated

JMH Roofing

Johnson Controls

Kirk Erectors, Inc.

Leach & Russell Mechanical

Long Electric Co., Inc.

Lytle Electric

Meade, Inc.

Messer Construction

Meyer Najem, Inc., Indianapolis Office

Midwest Associates of Indianapolis, Inc.

Miller-Eads Co., Inc.

M.J. Electric, IPC

M.J. Electric, LLC

Performance Contracting

Poettker Construction Company

Poynter Sheet Metal

PPMI Firestop, Inc.

Ritter Plumbing Company

River Town Construction, LLC

RLTurner

Robinson Trenching & Directional Boring Inc.

Safety Medic LLC

Santarossa Mosaic & Tile Co., Inc.

Scaffold King Rentals, Inc.

Shambaugh & Son, L.P.- Including subsidiaries:

- **Dalmatian Fire**
- **Ed Grace**
- **Havel**
- **ASG**
- **AS/CC**

Shiel Sexton Company, Inc.

Simms Painting Co., Inc.

Smock Fansler Corporation

Smoot Construction

Solid Platforms

SSI Services, LLC

STAR Environmental

Sterling Industrial, LLC

Sub-Surface of Indiana

Sullivan & Poore, Inc.

Summit Construction Co., Inc.

Superheat FGH Services, Inc.

The Blakley Corporation -Including subsidiaries:

- **Gates Company**
- **AWS**
- **Ceramic Tile and Terrazzo**

Thermal Solutions

The Skillman Corporation

The State Group Industrial USA Limited

Triangle Enterprises, Inc.

Turbine Master, Inc.

Turner Construction Company of Indiana, LLC

VFP Fire Systems

Wealing Brothers, LLC

Wright Tree Service

Wurster Construction Co., Inc.

JANUARY RATES

Aggregate Partnership Days Away Restricted and Transfer (DART) Rate: 0.43

Total Number of OSHA Cases with Days Away, Restriction or Transfer X 200,000

9

Total Number of Hours Worked by Partners

4,219,609

Aggregate Partnership Total Recordable Case (TRC) Rate: 0.71

Total Number of OSHA Recordable Incidents X 200,000

15

Total Number of Hours Worked by Partners

4,219,609

YTD RATES

Aggregate Partnership Days Away Restricted and Transfer (DART) Rate: 0.43

Total Number of OSHA Cases with Days Away, Restriction or Transfer X 200,000

9

Total Number of Hours Worked by Partners

4,219,609

Aggregate Partnership Total Recordable Case (TRC) Rate: 0.71

Total Number of OSHA Recordable Incidents X 200,000

15

Total Number of Hours Worked by Partners

4,219,609

Incident Number	Date	Incident Narrative
1	1/2023	(H) Slipped in elevator shaft while tied off causing a contusion to the knee.
2	1/2023	(H) Cleaning snow out of pickup causing lower back pain.
3	1/2023	(H) Cleaning chute of material and accidentally closed chute door on arm resulting in hospitalized and off work.
4	1/2023	(H) Worker was working in an JLG (MEWP) with tracks. The worker drove up the JLB up an incline, once the units center of gravity peaked the change in elevation, the unit moved downward quickly. The movement resulted in an catapulting action for the operator in the basket. He slammed his chin into the railing of the basket causing a broken jaw.
5	1/2023	(I) Employee was driving a forklift heading towards interior of building. While going over a small gap, forks became unhinged. While trying to fix the forks himself, one of the forks slipped and landed onto employee's foot.
6	1/2023	(I) Employee was in a boom lift, while driving forward, he hit a rut & the bucket lifted up a bit & he hit his head on the bar joist. Employee stated that he felt nauseous & threw up.
7	1/2023	(I) Employee was moving 6-inch pipe and the pipe got caught in table and that is when he felt the muscle strain in right shoulder and neck.
8	1/2023	(I) Employee had a 4-inch pike on the lift and was in the process of moving it and he got his left-hand pinky finger smashed.
9	1/2023	(I) The employee was handling fire suppressant pipe, in elevated aerial lift placing pipe into the hanger, began feeling wrist and hand pain.
10	1/2023	(J) While adding a tooth to a sheet metal brake the workers finger was on the underside of the tooth. At the time he was adding the tooth, the lever on the left side of the machine was not locked in place. With the lever not locked in place the clamping bar engaged pinching his finger underneath the tooth. He then pulled his finger out. The pinch and pull and the corner of the tooth created the laceration requiring stitches.
11	1/2023	(J) Tightening conduit resulted in pop occurring in right thumb.
12	1/2023	(J) During demo of HVAC equipment employee described pop in shoulder MRI scheduled.
13	1/2023	(J) While employee was drilling overhead concrete anchors, had on safety glasses, did not wear a face shield. Later after work employee said he felt like something was in his eye.
14	1/2023	(J) Filing cabinet tipped over onto retail employee causing undetermined back sprain .
15	1/2023	(J) Unbolting coupling for a gear box, over exertion when attempting to loosen bolts causing back strain.

*Companies on probation for not reporting statistics for January:	**Companies Suspended due to Not Current Status: Edwards Electrical & Mechanical
Companies removed from partnership: HMH Contractors, Inc.	Companies added to partnership: August Mack Environmental