



## **Indiana Department of Labor and CCS Monthly Partnership Report June 2021**

**The following companies are signatory to the IDOL/CCS Partnership Agreement:**

**AAA Roofing Co., Inc.**

**ABC Cutting Contractors, Inc.**

**Advanced Rescue Solutions**

**ATEC, INC.**

**AECOM Hunt**

**BMWC Constructors**

**Bowen Engineering Corporation**

**Brehob Corporation**

**Broady-Campbell, Inc.**

**Capital Machinery Systems**

**C&C Sheet Metal, LLC**

**Charah, LLC**

**CMS Corporation**

**D.A. Dodd, LLC**

**Denney Excavating Inc.**

**Edwards Electrical and Mechanical**

**Edwards Moving and Rigging, Inc.**

**Electric Plus**

**Empire Contractors**

**Essential Architectural Signs, Inc.**

**F.A. Wilhelm Construction Co., Inc.**

**Fargo Insulation Co., Inc.**

**F.E. Moran, Inc. Special Hazard Systems**

**Freitag-Weinhardt, Inc.**

**Garmong Construction**

**Gaylor Electric**

**Gribbins Insulation Co., Inc.**

**GroundBreakers Hydrovac Excavation**

**Harmon Construction**

**Harmon Steel, Inc.**

**Harrell-Fish Inc.**

**HMH Contractors, Inc.**

**Hoist & Crane Service Group, Inc.**

**Horning Roofing & Sheet Metal Co, LLC**

**Industrial Contractors Skanska, Inc.**

**Industrial Electric, Inc.**

**Inland Pipe Rehabilitation (IPR)**

**Interior Specialties, Inc.**

**J.F. Electric, Incorporated**

**JMH Roofing**

**Johnson Controls**

**Leach & Russell Mechanical**

**Long Electric Co., Inc.**

**Lytle Electric**

**Meade Electric Co., Inc.**

**Messer Construction**

**Meyer Najem, Inc., Indianapolis Office**

**Midwest Associates of Indianapolis, Inc.**

**Millennium Steel, Inc.**

**Miller-Eads Co., Inc.**

**M.J. Electric, IPC**

**M.J. Electric, LLC**

**Performance Contracting**

**Poynter Sheet Metal**

**Ritter Plumbing Company**

**River Town Construction, LLC**

**RLTurner**

**Shambaugh & Son, L.P.- Including subsidiaries:**

- **Dalmatian Fire**
- **Ed Grace**
- **Havel**
- **ASG**
- **AS/CC**

**Shiel Sexton Company, Inc.**

**Simms Painting Co., Inc.**

**Smoot Construction**

**SOFCO Erectors, Inc.**

**Solid Platforms**

**SSI Services, LLC**

**Sterling Industrial, LLC**

**Sub-Surface of Indiana**

**Sullivan & Poore, Inc.**

**Summit Construction Co., Inc.**

**The Blakley Corporation -Including subsidiaries:**

- **Gates Company**
- **AWS**
- **Ceramic Tile and Terrazzo**

**Thermal Solutions**

**The Skillman Corporation**

**The State Group Industrial USA Limited**

**Triangle Enterprises, Inc.**

**Turbine Master, Inc.**

**Turner Construction Company of Indiana, LLC**

**VFP Fire Systems**

**Weddle Bros. Construction Companies**

**Weigand Construction Company, Inc.**

**Wurster Construction Co., Inc.**

**JUNE RATES**

Aggregate Partnership Days Away Restricted and Transfer (DART) Rate: .47

Total Number of OSHA Cases with Days Away, Restriction or Transfer X 200,000

9

---

Total Number of Hours Worked by Partners

3,817,879

Aggregate Partnership Total Recordable Case (TRC) Rate: 1.73

Total Number of OSHA Recordable Incidents X 200,000

33

---

Total Number of Hours Worked by Partners

3,817,879

**YTD RATES**

Aggregate Partnership Days Away Restricted and Transfer (DART) Rate: .25

Total Number of OSHA Cases with Days Away, Restriction or Transfer X 200,000

30

---

Total Number of Hours Worked by Partners

23,999,096

Aggregate Partnership Total Recordable Case (TRC) Rate: 0.84

Total Number of OSHA Recordable Incidents X 200,000

101

---

Total Number of Hours Worked by Partners

23,999,096

<b>Incident Number</b>	<b>Date</b>	<b>Incident Narrative</b>
1	6/2021	(H) Employee was shoving a pipe into storage rack and the pipe got racked in between and he hurt his right picky finger in the process. Employee states he did have his gloves on but was still hurt. Finger was fractured and will need to see an orthopedic for further injury information.
2	6/2021	(I) Employee jumped off 10' stepladder which had begun to tip over as a result of his side-loading the ladder. Employee sustained a heel fracture.
3	6/2021	(I) Employee pinched thumb between equipment causing a fracture and laceration.
4	6/2021	(I) Employee was operating a saw and the saw ended up rolling off of the table which came back and hit him on his right index finger but did not cut it just has some swelling and bruising.
5	6/2021	(I) Employee was carrying a couple boxes and he felt sharp pain in his neck and shoulder
6	6/2021	(I) Employee was closing a roof hatch when he rotated his left forearm and pulled a muscle.
7	6/2021	(I) Employee walking out of warehouse, stepped down from ledge and rolled left ankle causing non-displaced fracture.
8	6/2021	(I) Employee was pushing a trash cart when she felt a pain in her lower area. Employee was diagnosed with a pro lapse.
9	6/2021	(I) While working in company yard, employee stepped off of transformer that was being scrapped and twisted left ankle. X-Ray was negative and employee was on restricted duty for 7 days.
10	6/2021	(J) Employee was carrying pipe up stairs when his boot caught on the step causing him to strike his knee on the stair causing a laceration.
11	6/2021	(J) Team member fell and suffered a minor abrasion on the elbow. Was administered first aid. The abrasion became red and swollen, so the team member was seen at a medical facility and prescribed an antibiotic to prevent infection.
12	6/2021	(J) Team member was moving some metal tubing without gloves and received a laceration to their finger.
13	6/2021	(J) While walking through maintenance shop employee grabbed onto lid of open barrel cutting left index finger. Employee was taken to local Urgent Care Center and required stitches.
14	6/2021	(J) While clearing brush the employee cross his wrist over the top of a chainsaw that the bar was not running at the time. It had a new chain that was very sharp and cut the employees wrist. Employee received four stiches.
15	6/2021	(J) Employee was hanging supports and fixtures for light in ceiling when he touch a live electrical wire causing an electrical burn to employees left hand.
16	6/2021	(J) Employee was installing insulation on a 1" refrigerant line. The refrigerant line protruded through a wall, and inside of that room the refringent line connected on top of a HVAC unit. Where the line connected on top of the unit, it 90 downward into a small cavity on the unit. The line was required to be insulated directly to where it ties into the unit. The small cavity was not large enough for the employee to climb down into, therefore our employee had to work from his knees or sit on his butt in order to access the lines. The employee had to lean down in order to insulate the line. While kneeling/sitting the employee had to bend at the waist and turn to get into the small cavity. While doing this the employee felt some stiffness in the back. The employee didn't think anything of it and continued working the remainder of the day. It was when he arrived home and began relaxing where he began to get stiff. Employee notified the safety manager Tuesday evening that he had some back pain associated to performing a task at work.
17	6/2021	(J) Employee was walking, slipped on ice, and struck right hip on the ground causing contusion to right hip.
18	6/2021	(J) Worker was lifting panel guts into enclosure when he heard 2 pops in right arm; was taken to Nova Clinic and has been referred to Ortho for possible torn bicep.

<b>19</b>	<b>6/2021</b>	(J) Toe fractured when caught under equipment
<b>20</b>	<b>6/2021</b>	(J) Hand punctured by metal sliver, antibiotics
<b>21</b>	<b>6/2021</b>	(J) Working on equipment, spring let loose causing laceration, stitches
<b>22</b>	<b>6/2021</b>	(J) Employee was drilling overhead when debris fell in his left eye. Employee was taken to the clinic for preventive measures and doctor prescribed an antibiotic.
<b>23</b>	<b>6/2021</b>	(J) Employee was struck in the shoulder by a dropped object from another contractor. Employee sought medical attention and was prescribed pain medicine for his contusion.
<b>24</b>	<b>6/2021</b>	(J) Employee was up in the air on the boom lift tying up the pipe & some of the dust flew off the coupling and got in his eye. Employee was wearing his Safety Glasses, but the debris got in between the cracks of the glasses.
<b>25</b>	<b>6/2021</b>	(J) Employee was in the process of hooking an enclosed trailer up to his truck. The hitch had not settled completely on the ball, and he used his hand to check to see if it was completely seated. The hitch shifted and his left index finger was crushed in the pinch point between the hitch and ball.
<b>26</b>	<b>6/2021</b>	(J) Employee was installing some hangers and back of his neck got cut by the rack in the crawl space he was working in.
<b>27</b>	<b>6/2021</b>	(J) Employee got some metal shavings in his eye.
<b>28</b>	<b>6/2021</b>	(J) Employee was carrying a pipe on his shoulder and got knocked off balance, fell onto his right shoulder.
<b>29</b>	<b>6/2021</b>	(J) Employee burned by anhydrous ammonia causing a 2nd degree burn to leg.
<b>30</b>	<b>6/2021</b>	(J) Employee was in contact with excess fine thread of stainless steel causing a laceration to their finger.
<b>31</b>	<b>6/2021</b>	(J) While attempting to remove the thermal detector tester from a solo extension pole, the screwdriver slipped and penetrated the flesh of employees' hand. Employee punctured/cut their hand.
<b>32</b>	<b>6/2021</b>	(J) While cutting a 2X4, a particle got in carpenter's eye. He states he was wearing safety glasses at the time.
<b>33</b>	<b>6/2021</b>	(J) Employee pinched finger between concrete form.

<b>*Companies not reporting statistics for June:</b>	<b>**Companies Suspended due to Not Current Status:</b>
<b>Companies removed from partnership:</b>  Brock Industrial Services, LLC	<b>Companies added to partnership:</b>  Capital Machinery Systems Inland Pipe Rehabilitation (IPR) M.J. Electric, IPC M.J. Electric, LLC